


**MKSUS282 Suspension for 4 Disabled Parking Bays. Request for maintenance of replacement gas to comply with current gas regulations from 26.07.21-30.07.21.**



14/07/21 Siu communicated with Saba Supervisor to suspend these 8 bays as temporary solution for disabled motorist to park. This would allow disabled motorist to park their vehicles in-between 2 bays, allowing enough access to get in/out of their vehicles. Also this allows the company to replace the gas at a safer distance away from the public.

Cadent Gas request the 4 disabled bays for suspension from 26.07.21-30.07.21.

Due to 1 way system, notices and tape/barrier to be in place in this location. This area would have to be closed.

**Company's response why they require the disabled bays.**

The gas kiosk we are replacing doesn't comply with the current gas regulations, and it contains asbestos which must be removed. Parking bays are required to position a skip, scaffolding lorry delivery, asbestos subcontractor, our van, and our Hiab delivery. Our Hiab is 12m long, and if we can't use the disabled bays, we will not be able to carry out the lift without blocking the car park driveway. It has a 1 way system and it's the only way to access the disabled bays. Can the disabled bays be temporary repositioned to the other side instead please?